Oil Field Environmental Incident Summary

Responsible Party: BOH Incorporated

Well Operator: MESA OIL SERVICES LLC

Well Name: CARL SPACKLER SWD 1

Field Name: SATHER LAKE Well File #: 90307

Date Incident:7/19/2014Time Incident:03:45Facility ID Number:County:MCKENZIETwp:149Rng:101Sec:30Qtr:

Location Description:

Submitted By: Thomas Norman Received By:

Contact Person: Tom Muth

P.O. Box 4419

Williston, ND 58802

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well:

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 20 Barrels 20 Barrels 20 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 3/19/2015 Clean Up Concluded: 7/20/2014

Risk Evaluation:

Upon securing the source of spill, measures to isolate and contain the spill were undertaken. No injuries occurred.

Areal Extent:

Potential Environmental Impacts:

Spill contaminated top soil outside the containment area but was confined to a roughly 20 foot by 20 foot area. Top soil is being removed and disposed of at an alternate facility.

Action Taken or Planned:

BOH was immediately notified of the spill resulting from their driver's negligence. Driver was subsequently terminated.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 7/21/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a truck overflow, remained on location according to the report. NDIC retains oversight.